



Lavori nella stazione di piazza Lima

Tipologia di risorsa: Photograph

Creatore: Publifoto

Data: 22.02.1962

Full description

Title: Lavori nella stazione di piazza Lima

Original title: 9° lotto. Lavori nella stazione di piazza Lima Description: Lo scatto mostra la sezione della stazione Lima durante i lavori. Si nota la copertura metallica e i palazzi .

Inscription: [1]- "9° lotto = Stazione Lima = Carpenteria Copertura zona 2"

Inscription: [2]- "Febbraio 1962 - 9° lotto - Lavori nella stazione di P.za Lima"

Inscription: "077369 // 22 FEB. 1962 // Foto-attualità Publifoto, viale Montello, 16 Milano. Telefoni 348.618 - 342.510"

Collection: Luigi Zaretti Collection

Client: Zaretti, Luigi

Date of creation: 22.02.1962

Place of creation: Milano

Name of creator: Publifoto (Attributed to)

Subjects Sbt: Cantieri edili, Stazioni metropolitane, Metropolitane, Operai

Subjects Getty AAT: Construction sites, Construction workers, Subways, Subway stations

Depicted place: Milano

Classification: 625.400

Reference: <http://metromilano.biblio.arc.usi.ch/>

Document type: Photographic material

Original technology: Analog

Specific document definition: Photograph

Material: Paper

Colour: Black-and-white

Polarity: Positive

Material type: Opaque

Process and technique: Gelatin silver process

Orientation and form: Landscape

Scheda immagine n. 197

06-06-2026 17:09:02

Work dimensions: 18x24 cm